



INSPEKTO
AUTONOMOUS MACHINE VISION

Pipe Rubber Ring Assembly

Inspection Use Case

Application

Assembly

Inspection Objective

Ensure rubber ring existence and insertion.

Potential Defect Types

Missing rubber ring, partly inserted ring

Permitted defects

White marks on the rubber ring

Part Description

Name

Pipe

Materials

Metal, Rubber

Part Size

5 cm diameter

Production process

Assembly

Industry

Sanitary

Using INSPEKTO S70

